

Cover Sheet



Assembly / Disassembly / Annual / Inspection Form

Mar 6, 2025

Form Type	INITIAL - Assembly / Annual
Crane Number	HC2208
Crane Manufacturer	Liebherr
Crane Model Number	LTR1220
Serial Number	096624
Machine Type	Crawler
Boom Type	Hydraulic Boom
Configuration	Main Boom
Job Number	241128: HC2208 (2025-03-10)
Main Boom Length	197 FEET
Jib Length	0 FEET
Upper CW	70 TONS
Central ballast	20 TONS
Parts of Line	8x1
Hour Meter Reading	10929



Track Hour Meter Reading	819
--------------------------	-----



Cover Sheet



Assembly / Disassembly / Annual / Inspection Form

Mar 6, 2025

Inspector's Name Christopher Haber

Inspector's Signature

A handwritten signature in black ink, appearing to read "CHABER", written over a horizontal line.

Customer's Name Brian smith

Customer's Email

Brian-smith2@hoffmancorp.com

Customer's Signature

A handwritten signature in black ink, appearing to read "Brian", written over a horizontal line.

Date of Inspection

Mar 6, 2025



Condition Inspection

Buckner or its representatives shall have the right at any time, without notice, during the Term to enter upon the premises or place where the Equipment is located and shall be given free access and afforded all necessary facilities for the purpose of inspecting the hours and condition of the Equipment. Such inspection shall not relieve Customer of any obligation under the Agreement and shall not constitute any waiver by Buckner of any obligations of Customer under the Agreement. Customer may not rely on such inspection in any way.

Cover Sheet



Assembly / Disassembly / Annual / Inspection Form

Mar 6, 2025

Total Number of Questions on Inspection	245
Total Number of Questions Answered	245
Percent Complete	100%
Total Number of Questions Not Answered	0
Number of Satisfactory (Green) Items	199
Number of Deficient (Red) Items	2
Number of Not Applicable (Grey) Items	33