


Cover Sheet



Assembly / Disassembly / Annual / Inspection Form

Apr 15, 2025

Form Type	INITIAL - Assembly / Annual
Crane Number	CR1227
Crane Manufacturer	Liebherr
Crane Model Number	LR11000
Serial Number	098277
Machine Type	Crawler
Boom Type	Lattice Boom
Configuration	Main Boom + Fixed Jib
Job Number	241042: CR1227 (2025-02-21)
Main Boom Length	108 METERS
Jib Length	12 METERS
Upper CW	250 TONS
Central ballast	130 TONS
Parts of Line	10
Hour Meter Reading	2429



Track Hour Meter Reading	129
--------------------------	-----



Cover Sheet



Assembly / Disassembly / Annual / Inspection Form

Apr 15, 2025

Inspector's Name Brian Tidwell

Inspector's Signature

A handwritten signature in black ink, appearing to read "B. Tidwell", written over a horizontal line.

Customer's Name Johnathan rutherford

Customer's Email Jarutherford@quantaser
vices.com

Customer's Signature

A handwritten signature in black ink, appearing to read "Johnathan Rutherford", written over a horizontal line.

Date of Inspection Apr 6, 2025



Condition Inspection

Buckner or its representatives shall have the right at any time, without notice, during the Term to enter upon the premises or place where the Equipment is located and shall be given free access and afforded all necessary facilities for the purpose of inspecting the hours and condition of the Equipment. Such inspection shall not relieve Customer of any obligation under the Agreement and shall not constitute any waiver by Buckner of any obligations of Customer under the Agreement. Customer may not rely on such inspection in any way.

Cover Sheet



Assembly / Disassembly / Annual / Inspection Form

Apr 15, 2025

Total Number of Questions on Inspection	256
Total Number of Questions Answered	256
Percent Complete	100%
Total Number of Questions Not Answered	0
Number of Satisfactory (Green) Items	226
Number of Deficient (Red) Items	0
Number of Not Applicable (Grey) Items	19